


Front Camera - Inside view of EUT



Report no. ETLE140714.1032, Page D1 of D12




Front Camera - Inside view of EUT



Report no. ETLE140714.1032, Page D2 of D12




Front Camera - Top side view of main board



Report no. ETLE140714.1032, Page D3 of D12




Front Camera - Bottom side view of main board



Report no. ETLE140714.1032, Page D4 of D12




Front Camera - Top side view of power board



Report no. ETLE140714.1032, Page D5 of D12




Front Camera - Bottom side view of power board



Report no. ETLE140714.1032, Page D6 of D12




Front Camera - Top side view of RF Module



Report no. ETLE140714.1032, Page D7 of D12



Front Camera - Bottom side view of RF Module



Report no. ETLE140714.1032, Page D8 of D12




Front Camera - View of display panel



Report no. ETLE140714.1032, Page D9 of D12




Rear Camera - Inside view of EUT



Report no. ETLE140714.1032, Page D10 of D12




Rear Camera - Top side view of main board



Report no. ETLE140714.1032, Page D11 of D12



Rear Camera - Bottom side view of main board



Report no. ETLE140714.1032, Page D12 of D12