



Inside view of EUT



Report no. ETLT160404.0037, Page D1 of D11




Top side view of main board



Report no. ETLT160404.0037, Page D2 of D11




Top side view of main board (open cap)



Report no. ETLT160404.0037, Page D3 of D11



Bottom side view of main board




Report no. ETLT160404.0037, Page D4 of D11

Head Office: #371-51, Gasan-dong, Geumcheon-gu, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-0788

Open site: #499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, Korea



Bottom side view of main board (open cap)



Report no. ETLT160404.0037, Page D5 of D11




Top side view of sub main board



Report no. ETLT160404.0037, Page D6 of D11



Bottom side view of sub main board





Report no. ETLT160404.0037, Page D7 of D11

Open site: #499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, Korea



View of GPS board






Report no. ETLT160404.0037, Page D8 of D11




View of GPS board (open cap)






Top view of WIFI module and antenna



Bottom view of WIFI module



Report no. ETLT160404.0037, Page D10 of D11



Bottom of WIFI module (open cap)

