

Inside view of EUT



Report no. ETLT180206.0021, Page D1 of D9




Top side view of main board



Report no. ETLT180206.0021, Page D2 of D9



Bottom side view of main board



Report no. ETLT180206.0021, Page D3 of D9



Bottom side view of main board (open cap)



Report no. ETLT180206.0021, Page D4 of D9

 $\textbf{Head Office: } \$371\text{-}51\text{, Gasan-dong, Geumcheon-gu, Seoul, } 153\text{-}803\text{, Korea} \qquad \text{Tel: } 82\text{-}2\text{-}858\text{-}0786 \qquad \text{Fax: } 82\text{-}2\text{-}858\text{-}0788 \\ \textbf{Seoul, } \$28\text{-}2\text{-}858\text{-}0788 \\$

Open site: #499-1, Sagot-ri, Seosin-myeon, Hwaseong-si, Gyeonggi-do, 445-882, Korea



Top side view of sub main board



Report no. ETLT180206.0021, Page D5 of D9



Bottom side view of sub main board




Report no. ETLT180206.0021, Page D6 of D9

 $\textbf{Head Office: } \$371\text{-}51\text{, Gasan-dong, Geumcheon-gu, Seoul, } 153\text{-}803\text{, Korea} \qquad \text{Tel: } 82\text{-}2\text{-}858\text{-}0786 \qquad \text{Fax: } 82\text{-}2\text{-}858\text{-}0788 \\ \text{Tel: } 82\text{-}2\text{-}858\text{-}0786 \\ \text{Tel: } 82\text{-}2\text$



View of Camera Module






Report no. ETLT180206.0021, Page D7 of D9



View of Camera Module Board







Report no. ETLT180206.0021, Page D8 of D9



Top view of WIFI module and antenna



Top view of WIFI module (open cap)



Report no. ETLT180206.0021, Page D9 of D9