


BLACKVUE SPORT - Inside view of EUT



Report no. ETLE130808.0911, Page D1 of D12




BLACKVUE SPORT - Top side view of main board



Report no. ETLE130808.0911, Page D2 of D12




BLACKVUE SPORT - Bottom side view of main board



Report no. ETLE130808.0911, Page D3 of D12




BLACKVUE SPORT - Bottom side view of main board (without Camera lens)



Report no. ETLE130808.0911, Page D4 of D12




BLACKVUE SPORT - Top side view of sub board



Report no. ETLE130808.0911, Page D5 of D12



BLACKVUE SPORT - Bottom side view of sub board



Report no. ETLE130808.0911, Page D6 of D12




BLACKVUE SPORT - Top side view of Chip Antenna




Report no. ETLE130808.0911, Page D7 of D12



BLACKVUE SPORT - Top side view of Camera lens




BLACKVUE SPORT - Bottom side view of Camera lens



Report no. ETLE130808.0911, Page D8 of D12




BLACKVUE SPORT LCD - Inside view of EUT



Report no. ETLE130808.0911, Page D9 of D12




BLACKVUE SPORT LCD - Top side view of main board



Report no. ETLE130808.0911, Page D10 of D12



BLACKVUE SPORT LCD - Bottom side view of main board




Report no. ETLE130808.0911, Page D11 of D12



BLACKVUE SPORT LCD - View of LCD panel





Report no. ETLE130808.0911, Page D12 of D12