

Appendix B. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53A48 Page Number : B1 of B2
Report Issued Date : Sep. 23, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR662003A






Report No.: FR662003A


<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL : 86-0512-5790-0158 FAX : 86-0512-5790-0958 FCC ID : YCNK53A48 Page Number : B2 of B2
Report Issued Date : Sep. 23, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1