

Appendix D. Setup Photographs

<Conducted Emission> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D1 of D3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02
Report Template No.: BU5-FR15CWL Version 1.1

Report No.: FR662816C







<Radiated Emission>

Z Plane for WLAN 2.4GHz 802.11g

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D2 of D3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02
Report Template No.: BU5-FR15CWL Version 1.1


Report No.: FR662816C






X Plane for WLAN 2.4GHz 802.11b/n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : D3 of D3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02
Report Template No.: BU5-FR15CWL Version 1.1

Report No.: FR662816C