Appendix D. Test Setup Photos





Report No. : FA491713

Right Cheek

Right Tilted





Left Cheek Left Tilted

 $\mathsf{TEL} : 86\text{-}0512\text{-}5790\text{-}0158 \, / \, \mathsf{FAX} : 86\text{-}0512\text{-}5790\text{-}0958$

FCC ID: YCNS856

Issued Date : Oct. 16, 2014 Form version : 140820





Report No. : FA491713

Back of the DUT with Phantom 0 cm Gap

Back of the DUT with Phantom 1 cm Gap





Bottom Side of the DUT with Phantom 0 cm Gap Bottom Side of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap (with / headset)


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

FCC ID: YCNS856

Issued Date : Oct. 16, 2014

: 140820 Form version





Front of the DUT with Phantom 1 cm Gap

Top Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

FCC ID: YCNS856

Issued Date : Oct. 16, 2014

Form version : 140820