
## **Appendix C. Setup Photographs**


## <Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : C1 of C2
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: FG5D0806A


Report Template No.: BU5-FG22/24/27/90 Version 1.1

## X Plane for 24E.27L

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : C2 of C2
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: FG5D0806A

Report Template No.: BU5-FG22/24/27/90 Version 1.1