
Appendix C. Setup Photographs


<Radiated Emission>

X Plane for 22H

LF



HF




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : C1 of C3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02
Report Template No.: BU5-FG22/24/27 Version 1.1


Report No. : FG662816A

X Plane for 24E

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : C2 of C3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02

Report No. : FG662816A


Report Template No.: BU5-FG22/24/27 Version 1.1

Y Plane for 27L

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : C3 of C3
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02

Report No.: FG662816A

Report Template No.: BU5-FG22/24/27 Version 1.1