

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : C1 of C3
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR631107-01C






Report No. : FR631107-01C

<Radiated Emission>

Z Plane for WLAN 2.4G 802.11b/g

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : C2 of C3
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.2






X Plane for WLAN 2.4G 802.11n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : C3 of C3
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR631107-01C