

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48 Page Number : C1 of C3
Report Issued Date : Dec. 11, 2015
Report Version : Rev. 01


Report No.: FR5N2306C




<Radiated Emission>

X Plane for WLAN 802.11b

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48 Page Number : C2 of C3
Report Issued Date : Dec. 11, 2015
Report Version : Rev. 01

Report No.: FR5N2306C




Z Plane for WLAN 802.11g/n

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48 Page Number : C3 of C3
Report Issued Date : Dec. 11, 2015
Report Version : Rev. 01

Report No.: FR5N2306C