

## Report No.: FR5N2306D

## **Appendix D. Setup Photographs**


## <Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48 Page Number : D1 of D2
Report Issued Date : Dec. 11, 2015
Report Version : Rev. 01



## <Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48 Page Number : D2 of D2
Report Issued Date : Dec. 11, 2015
Report Version : Rev. 01

Report No.: FR5N2306D