

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : C1 of C3
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.1


Report No.: FR5D0806-02C




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : C2 of C3
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.1


Report No.: FR5D0806-02C






Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : C3 of C3
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.1

Report No.: FR5D0806-02C