

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Report No.: FR5D0806-01B

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L37

790-0958 Report Version : Rev. 01 8020L37 Report Template No.: BU5-FR15CBT4.0 Version 1.1

Page Number

B1 of B2


Report Issued Date : Feb. 03, 2016



<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L37 Page Number : B2 of B2
Report Issued Date : Feb. 03, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.1

Report No.: FR5D0806-01B