1. External Photograph of EUT

Brand Name: lenovo; Model Name: Lenovo S820

Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 1 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01



Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820

Page Number : 2 of 28 Report Issued Date : Jun. 14, 2013 Report Version : Rev. 01

Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 3 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01

Report No.: EP342509




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 4 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01

Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 5 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01

Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 6 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: lenovo; Model Name: Lenovo S820

Report No.: EP342509

List of Accessory:

| Specification of Accessory | | |
|----------------------------|------------------|--|
| IAC Adanter | Brand Name | lenovo |
| | Model Name | C-P34 |
| Battery | Brand Name | lenovo |
| | Model Name | BL210 |
| USB Cable 1 | Signal Line Type | 1.0m, non-shielded cable, without core |
| USB Cable 2 | Signal Line Type | 1.0m, non-shielded cable, without core |
| Earphone | Signal Line Type | 1.0m, non-shielded cable |

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 7 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01

Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820

Page Number : 8 of 28 Report Issued Date : Jun. 14, 2013

Report Version : Rev. 01

Report No.: EP342509



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820 Page Number : 9 of 28
Report Issued Date : Jun. 14, 2013
Report Version : Rev. 01



Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820

Page Number : 10 of 28 Report Issued Date : Jun. 14, 2013 Report Version : Rev. 01



Report No.: EP342509



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS820

Page Number : 11 of 28 Report Issued Date : Jun. 14, 2013 Report Version : Rev. 01