Appendix D. SAR Test Setup Photos





Report No. :FA662816-04

Right Cheek







Left Cheek Left Tilted






Report No. : FA662816-04

Front, Test Separation 10 mm

Back, Test Separation 10 mm







Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm



Back with Headset, Test Separation 10 mm

TEL: 86-755-8637-9589/ FAX: 86-755-8637-9595

Issued Date: Dec. 21, 2016 Form version. : 160427 FCC ID: YCNK33B36 Page D2 of D2

Appendix E. Product Equality Declaration

Report No. : FA662816-04

 SPORTON INTERNATIONAL (SHENZHEN) INC.
 Page E1 of E1
 Issued Date
 : Dec. 21, 2016

 TEL: 86-755-8637-9589/ FAX: 86-755-8637-9595
 Form version.
 : 150416

Lenovo Mobile Communication Technology Ltd.

No.999, Qishan North 2nd Road, Information & Optoelectronics Park, Torch Hi-tech Industry Development Zone, Xiamen, P.R.China

Tel: 86-10-58866181; Fax: 86-10-56720293

Date: November 11, 2016

Product Equality Declaration


We, Lenovo Mobile Communication Technology Ltd., declare on our sole responsibility for the product of Lenovo K33b36 (Dual SIMs) &K33b37 (Single SIM) as below:

The differences between Lenovo K33b36 (Dual SIMs) &K33b37 (Single SIM) and previous as below:

1. LCD panel changed.

Object	Original	Variant
LCD	Item number code for	Item number code for TL050VVMP04-00
	TL050VVXP14-00	
	Item number code for	Item number code for TL050VVMP06-00
	TL050VVXP16-00	

2. This difference is normal difference.



Except listings above, the others are all the same.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely yours,

Contact Person: Li xihong

Xihong Li

COMPANY: Lenovo Mobile Communication Technology Ltd.

Tel: 18910866181 Fax: 86-10-57874529 E-Mail: lixh5@lenovo.com