


**Report No.: FA331902** 

## Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA706 Page Number : D1 of D2
Report Issued Date : Apr. 22, 2013
Report Version : Rev. 01



**Report No. : FA331902** 

## **Antenna Location:**



Antennas	Length	Width
WWAN Antenna (Tx/Rx)	4.6cm	0.7cm
WLAN & Bluetooth Antenna (Tx/Rx)	1.0cm	0.4cm
EUT	13.4cm	6.7cm

The shortest distance between the Tx antennas		
WWAN Antenna (Tx/Rx) to WLAN & Bluetooth Antenna (Tx/Rx)	11.7cm	

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA706 Page Number : D2 of D2
Report Issued Date : Apr. 22, 2013
Report Version : Rev. 01



## Report No. : FA331902

## Appendix E. Test Setup Photos



**Right Cheek** 









**Left Tilted** 



Front of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA706 Page Number : E1 of E2
Report Issued Date : Apr. 22, 2013

Report Version : Rev. 01





Front of the DUT with Phantom 1 cm Gap (w/headset)



Report No.: FA331902

Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



**Bottom Side of the DUT with Phantom 1 cm Gap** 

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA706

Page Number : E2 of E2 Report Issued Date: Apr. 22, 2013

Report Version : Rev. 01