Appendix C. Setup Photographs

<Radiated Emission>

Y Plane for 22H

LF






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53B3 Page Number : C1 of C3
Report Issued Date : Sep. 12, 2016
Report Version : Rev. 01


Report No.: FG662005A

Report Template No.: BU5-FG22/24/27 Version 1.1



Y Plane for 24E

LF







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53B3 Page Number : C2 of C3
Report Issued Date : Sep. 12, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1

Report No.: FG662005A

Z Plane for 27L

LF





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53B3 Page Number : C3 of C3
Report Issued Date : Sep. 12, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.1