Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A1 of A4
Report Issued Date : Oct. 16, 2014

Report No.: FR491713C


Report Version : Rev. 01




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A2 of A4
Report Issued Date : Oct. 16, 2014
Report Version : Rev. 01

Report No.: FR491713C




Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A3 of A4
Report Issued Date : Oct. 16, 2014
Report Version : Rev. 01

Report No.: FR491713C




Z Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A4 of A4 Report Issued Date : Oct. 16, 2014

Report No. : FR491713C

Report Version : Rev. 01