
3. Internal Photograph of EUT


Brand Name: Lenovo; Model Name: Lenovo A6020I36

Report No.: EP5D0806



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 12 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 13 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01



Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36

Page Number : 14 of 31 Report Issued Date : Jan. 06, 2016 Report Version : Rev. 01



Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36

Page Number : 15 of 31 Report Issued Date : Jan. 06, 2016 Report Version : Rev. 01



Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36

Page Number : 16 of 31 Report Issued Date : Jan. 06, 2016 Report Version : Rev. 01



Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36

Page Number : 17 of 31 Report Issued Date : Jan. 06, 2016 Report Version : Rev. 01



Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36

Page Number : 18 of 31 Report Issued Date : Jan. 06, 2016

Report Version : Rev. 01



Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36

Page Number : 19 of 31 Report Issued Date : Jan. 06, 2016

Report Version : Rev. 01

Report No.: EP5D0806



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 20 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 21 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 22 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 23 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 24 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 25 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01


Report No.: EP5D0806



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 26 of 31
Report Issued Date : Jan. 06, 2016


Report Version : Rev. 01

Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 27 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 28 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 29 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01


Report No.: EP5D0806



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 30 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: EP5D0806



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 31 of 31
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01