

Appendix D. Setup Photographs

<Conducted Emission> Mode 2



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33A48 Page Number : D1 of D2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.1

Report No.: FR662815C







<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33A48 Page Number : D2 of D2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.1

Report No.: FR662815C