

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : B1 of B2
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.2

Report No.: FR631107-01B







<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : B2 of B2
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.2

Report No.: FR631107-01B