

Appendix D. Setup Photographs

<Conducted Emission>

Mode 2



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53B3 Page Number : D1 of D3
Report Issued Date : Sep. 12, 2016
Report Version : Rev. 01


Report No.: FR662005C




<Radiated Emission>

X Plane for 802.11b Tx

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53B3 Page Number : D2 of D3
Report Issued Date : Sep. 12, 2016
Report Version : Rev. 01

Report No.: FR662005C




Z Plane for 802.11g/n20 Tx

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53B3 Page Number : D3 of D3
Report Issued Date : Sep. 12, 2016
Report Version : Rev. 01

Report No.: FR662005C