

Report No.: FA391104

Appendix D. SAR Test Setup Photos





Right Cheek

Right Tilted





Left Cheek **Left Tilted**

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YCNS960

Page Number : D1 of D2 Report Issued Date: Oct. 08, 2013

Report Version : Rev. 01





Report No.: FA391104

Front, Test Separation 1 cm

Back, Test Separation 1 cm



Right Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Bottom Side, Test Separation 1 cm

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YCNS960

Page Number : D2 of D2 Report Issued Date: Oct. 08, 2013 Report Version : Rev. 01