Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS90L Page Number : A1 of A2
Report Issued Date : Nov. 26, 2014

Report No.: FR4N0501A


Report Version : Rev. 01




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS90L Page Number : A2 of A2 Report Issued Date : Nov. 26, 2014

Report No.: FR4N0501A

Report Version : Rev. 01