



Report No.: FR5N2306F

Appendix C. Setup Photographs

<Conducted Emission> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48

: C1 of C2 Page Number Report Issued Date: Dec. 11, 2015 Report Version : Rev. 01







<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA7010A48 Page Number : C2 of C2
Report Issued Date : Dec. 11, 2015
Report Version : Rev. 01

Report No.: FR5N2306F