

## Report No.: FA361405

## Appendix D. **Test Setup Photos**





**Right Cheek** 

**Right Tilted** 





Left Cheek

**Left Tilted** 

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA516

Page Number : D1 of D2 Report Issued Date: Jun. 26, 2013

Report Version : Rev. 01








Front of the DUT with Phantom 1 cm Gap



**Report No. : FA361405** 

Back of the DUT with Phantom 1 cm Gap




Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap for Headset

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA516

Page Number : D2 of D2 Report Issued Date: Jun. 26, 2013 Report Version : Rev. 01