
# Appendix A. Setup Photographs


<Radiated Emission>

Z Plane for 24E

LF




HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A1 of A4
Report Issued Date : Oct. 16, 2014
Report Version : Rev. 01

Report No.: FG491713B




### Y Plane for 27L

LF



# HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A2 of A4
Report Issued Date : Oct. 16, 2014
Report Version : Rev. 01




### X Plane for 27M

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A3 of A4
Report Issued Date : Oct. 16, 2014
Report Version : Rev. 01

Report No.: FG491713B

### Report No.: FG491713B

### Y Plane for 27H

LF



# HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNS856 Page Number : A4 of A4
Report Issued Date : Oct. 16, 2014
Report Version : Rev. 01