


Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK900 Page Number : B1 of B2
Report Issued Date : Apr. 28, 2013
Report Version : Rev. 01


Report No.: FR332604A



<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK900 Page Number : B2 of B2
Report Issued Date : Apr. 28, 2013
Report Version : Rev. 01

Report No.: FR332604A