

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6000L Page Number : B1 of B2
Report Issued Date : Jan. 22, 2015
Report Version : Rev. 01

Report No.: FR4N1001B






Report No.: FR4N1001B

<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6000L

Page Number : B2 of B2 Report Issued Date: Jan. 22, 2015 Report Version

: Rev. 01