

# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : B1 of B2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02

Report No.: FR662816A


Report Template No.: BU5-FR15CBT Version 1.1




### <Radiated Emission>

#### **Z** Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33B36 Page Number : B2 of B2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 02
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR662816A