
3. Internal Photograph of EUT

Brand Name: Lenovo; Model Name: Lenovo A6020I36

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 12 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 13 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Brand Name: Lenovo; Model Name: Lenovo A6020I36




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 14 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 15 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 16 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 17 of 30
Report Issued Date : Feb. 02, 2016

Report Version : Rev. 01

DE OF OS OF

Brand Name: Lenovo; Model Name: Lenovo A6020I36

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 18 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 19 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 20 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 21 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01


Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 22 of 30
Report Issued Date : Feb. 02, 2016


Report Version : Rev. 01

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 23 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 24 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 25 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 26 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 27 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 28 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 29 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01

Report No.: EP5D0806-02



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNA6020L36 Page Number : 30 of 30
Report Issued Date : Feb. 02, 2016
Report Version : Rev. 01