

Appendix D. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53A48 Page Number : D1 of D3
Report Issued Date : Sep. 23, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.3


Report No.: FR662003B




<Radiated Emission>

X Plane for Bluetooth v4.0 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53A48 Page Number : D2 of D3
Report Issued Date : Sep. 23, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.3

Report No.: FR662003B


FCC RF Test Report

Z Plane for Bluetooth v4.2 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK53A48 Page Number : D3 of D3
Report Issued Date : Sep. 23, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.3

Report No.: FR662003B