Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33A48

Page Number : C1 of C2 Report Issued Date: Sep. 05, 2016 Report Version : Rev. 01

Report No.: FG662815A

Report Template No.: BU5-FG22/24 Version 1.2


Report No. : FG662815A

X Plane for 24E

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33A48 Page Number : C2 of C2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.2