
1. External Photograph of EUT

Brand Name: Lenovo / Model Name: Lenovo K10a40

Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 1 of 50

Report Issued Date : Apr. 20, 2016

Report Version : Rev. 01




Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40

Page Number : 2 of 50 Report Issued Date : Apr. 20, 2016 Report Version : Rev. 01


Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 3 of 50 Report Issued Date : Apr. 20, 2016

Report Version : Rev. 01

Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 4 of 50 Report Issued Date : Apr. 20, 2016

Report Version

: Rev. 01







TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40

Page Number : 5 of 50 Report Issued Date : Apr. 20, 2016

Report Version : Rev. 01

Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 6 of 50
Report Issued Date : Apr. 20, 2016

Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: Lenovo / Model Name: Lenovo K10a40

Report No.: EP631107-01

Specification of Accessory		
IAC Adanter	Brand Name	Lenovo
	Model Name	C-P56
Battery	Brand Name	Lenovo
	Model Name	BL259
Earphone	Signal Line Type	1.24m non-shielded without core
USB Cable	Signal Line Type	1.02m shielded without core

Remark:

- 1. For accessories equipped with this EUT, please refer to the following photos.
- 2. After pre-scan two type of EUT, we found test result of the Dual SIM Card (16G) (SIM1) was the worse, so we chose the Dual SIM Card (16G) (SIM1) to perform all tests

 ${\it SPORTON\ INTERNATIONAL\ (KUNSHAN)\ INC.}$

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 7 of 50
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01

Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 8 of 50
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01

Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40 Page Number : 9 of 50
Report Issued Date : Apr. 20, 2016
Report Version : Rev. 01



Report No.: EP631107-01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40

Page Number : 10 of 50 Report Issued Date : Apr. 20, 2016 Report Version : Rev. 01



Report No.: EP631107-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK10A40

: 11 of 50 Page Number Report Issued Date : Apr. 20, 2016

Report Version : Rev. 01