

Appendix D. Setup Photographs

<Conducted Emission>

Mode 2



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33A48 Page Number : D1 of D2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 01

Report No.: FR662815B


Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YCNK33A48 Page Number : D2 of D2
Report Issued Date : Sep. 05, 2016
Report Version : Rev. 01

Report No.: FR662815B

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2