


Appendix B. Setup Photographs

<Conducted Emission>



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 Page Number : B1 of B5
Report Issued Date : Oct. 11, 2010

Report Version : Rev. 01







Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 Page Number : B2 of B5
Report Issued Date : Oct. 11, 2010
Report Version : Rev. 01




<Radiated Emission>

Mode 1~3



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 Page Number : B3 of B5
Report Issued Date : Oct. 11, 2010
Report Version : Rev. 01





Remote View

Mode 4




Front View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 Page Number : B4 of B5
Report Issued Date : Oct. 11, 2010
Report Version : Rev. 01





Rear View



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 Page Number : B5 of B5
Report Issued Date : Oct. 11, 2010
Report Version : Rev. 01