

Report No. : FR041501

Appendix B. Setup Photographs

<Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 Page Number : B1 of B4
Report Issued Date : May 17, 2010

Report Version : Rev. 01





Report No. : FR041501



Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 Page Number : B2 of B4
Report Issued Date : May 17, 2010
Report Version : Rev. 01






Report No.: FR041501

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 Page Number : B3 of B4
Report Issued Date : May 17, 2010
Report Version : Rev. 01





Report No. : FR041501



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 Page Number : B4 of B4
Report Issued Date : May 17, 2010
Report Version : Rev. 01