1. External Photograph of EUT


Brand Name: bryton / Model Name: Rider 50

Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 1 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 2 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501

Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 3 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 4 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 5 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 6 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: bryton / Model Name: Rider 50

Report No.: EP041501

List of Accessory:

List of Accessory.		
Specification of Accessory		
AC Adapter	Brand Name	PHIHONG
	Model Name	PSA05F-050Q-H
	Power Rating	I/P:100-240Vac, 50-60Hz, 0.2A;
		O/P: 5Vdc, 1A
Battery	Brand Name	LICO
	Model Name	H11ND001A
	Power Rating	3.7Vdc, 1200mAh
	Туре	Li-ion
USB Cable	Brand Name	AMAX
	Signal Line Type	0.4 meter shielded cable with ferrite core
Cadence 1	Brand Name	IDT
	Model Name	AD202
	FCC ID	NMTAD202
	IC	3277A-AD202
Cadence 2	Brand Name	Dayton
	Model Name	BKM2G
	FCC ID	04GBKSPCD
	IC	7666A-BKSPCD
Heart Rate monitor 1	Brand Name	IDT
	Model Name	SZ990
	FCC ID	NMTSZ990
	IC	3277A-SZ990
Heart Rate monitor 2	Brand Name	Dayton
	Model Name	SHRM1G
	FCC ID	04GHRMHW1G
	IC	7666A-HRMHW1G

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 7 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01




Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 8 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 9 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01




Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 10 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01


Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 11 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 12 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 13 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 14 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 15 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



Report No.: EP041501




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 16 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 17 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 18 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 19 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 20 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 21 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 22 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01



Report No.: EP041501




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 23 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 24 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01



Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50

Page Number : 25 of 38 Issued Date : May 17, 2010 Report Version : Rev. 01

Report No.: EP041501



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER50 IC: 8957A-RIDER50 Page Number : 26 of 38
Issued Date : May 17, 2010
Report Version : Rev. 01