## 1. External Photograph of EUT

Brand Name: bryton / Model Name: Rider 30

Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 1 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02



Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 2 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02

## 2. Photograph of Accessory

Brand Name: bryton / Model Name: Rider 30

Report No.: EP091316

**List of Accessory:** 

List of Accessory.		
Specification of Accessory		
AC Adapter	Brand Name	PHIHONG
	Model Name	PSA05F-050Q
Battery	<b>Brand Name</b>	BYD
	Model Name	Warsaw
USB Cable	<b>Brand Name</b>	AMAX
	Model Name	N/A
Cadence 1	<b>Brand Name</b>	IDT
	Model Name	AD202
Cadence 2	<b>Brand Name</b>	Dayton
	Model Name	BKM2G
Heart Rate monitor 1	<b>Brand Name</b>	IDT
	Model Name	SZ990
Heart Rate monitor 2	Brand Name	Dayton
	Model Name	SHRM1G
Speed	Brand Name	Dayton
	Model Name	BKM1G

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 3 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02

Report No.: EP091316



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 4 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02

Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 5 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30

Page Number : 6 of 16 Report Issued Date : Oct. 18, 2010 Report Version : Rev. 02

Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30

Page Number : 7 of 16 Report Issued Date : Oct. 18, 2010 Report Version : Rev. 02

Report No.: EP091316

Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 8 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02

Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 9 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02

Report No.: EP091316



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 10 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02



Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30

: 11 of 16 Page Number Report Issued Date : Oct. 18, 2010 Report Version : Rev. 02

Report No.: EP091316



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 12 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02

Report No.: EP091316



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YDM-RIDER30 IC: 8957A-RIDER30 Page Number : 13 of 16
Report Issued Date : Oct. 18, 2010
Report Version : Rev. 02