

# Appendix B. Setup Photographs

# <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : B1 of B3
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: FR322149-01C




## Report No.: FR322149-01C


## <Radiated Emission>

#### **Z** Plane

LF







SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : B2 of B3
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01




## <Radiated Emission>

#### X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : B3 of B3
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: FR322149-01C