
3. Internal Photograph of EUT

Brand Name: DT Research Inc. / Model Name: DT398

Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 8 of 28

Report Issued Date : Mar. 30, 2013 Report Version : Rev. 01

Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 9 of 28

Report Issued Date : Mar. 30, 2013 Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 10 of 28

Report Issued Date : Mar. 30, 2013

Report No.: EP322149




Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 11 of 28 Report Issued Date : Mar. 30, 2013


Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 12 of 28
Report Issued Date : Mar. 30, 2013



Report No.: EP322149




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B

Page Number : 13 of 28

Report Issued Date : Mar. 30, 2013



Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 14 of 28

Report Issued Date : Mar. 30, 2013

Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 15 of 28
Report Issued Date : Mar. 30, 2013
Report Version : Rev. 01

Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 16 of 28
Report Issued Date : Mar. 30, 2013
Report Version : Rev. 01

Report No.: EP322149




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 17 of 28
Report Issued Date : Mar. 30, 2013




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 18 of 28 Report Issued Date : Mar. 30, 2013

Report No.: EP322149






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 19 of 28
Report Issued Date : Mar. 30, 2013
Report Version : Rev. 01



Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B

: 20 of 28 Page Number Report Issued Date : Mar. 30, 2013



WWAN Main Antenna

80 ASM 82 TITZIOR


80 ASM 82 TIT

 ${\it SPORTON\,INTERNATIONAL\,INC}.$

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 21 of 28 Report Issued Date : Mar. 30, 2013


Report No.: EP322149

Report No.: EP322149



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 22 of 28
Report Issued Date : Mar. 30, 2013
Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 23 of 28
Report Issued Date : Mar. 30, 2013
Report Version : Rev. 01



Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 24 of 28 Report Issued Date : Mar. 30, 2013



Brand Name: DT Research Inc. / Model Name: DT398 **WLAN Main Antenna BELLISTALS**

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B

Page Number : 25 of 28 Report Issued Date : Mar. 30, 2013

Report No.: EP322149



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 26 of 28 Report Issued Date : Mar. 30, 2013

: Rev. 01

Report Version

Report No.: EP322149

Report No.: EP322149




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B

Page Number : 27 of 28 Report Issued Date : Mar. 30, 2013



Report No.: EP322149



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800B Page Number : 28 of 28
Report Issued Date : Mar. 30, 2013