

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600C Page Number : B1 of B2
Report Issued Date : Jan. 20, 2015
Report Version : Rev. 01

Report No.: FR491670-01A

Report Template No.: BU5-FR15CBT Version 1.0



Report No.: FR491670-01A

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600C Page Number : B2 of B2
Report Issued Date : Jan. 20, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0