FCC RF Test Report

APPLICANT : DT Research Inc.
EQUIPMENT : Mobile Tablet
BRAND NAME : DT Research Inc.

MODEL NAME : DT398H FCC ID : YE3800C

STANDARD : FCC 47 CFR Part 2, 22(H), 24(E) CLASSIFICATION : PCS Licensed Transmitter (PCB)

The product was received on Sep. 16, 2014 and testing was completed on Dec. 18, 2014. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the test procedures given in ANSI / TIA / EIA-603-C-2004 and has been in compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL INC., the test report shall not be reproduced except in full.

Reviewed by: Joseph Lin / Supervisor

Approved by: Jones Tsai / Manager

SPORTON INTERNATIONAL INC.

No. 52, Hwa Ya 1st Rd., Hwa Ya Technology Park, Kwei-Shan Hsiang, Tao Yuan Hsien, Taiwan, R.O.C.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 1 of 62

1190

Report No.: FG491670A

Report Issued Date: Jan. 06, 2015
Report Version: Rev. 01

TABLE OF CONTENTS

RE	EVISIO	N HISTORY	3
sι	JMMAI	RY OF TEST RESULT	4
1		ERAL DESCRIPTION	
١			
	1.1	Applicant	
	1.2	Manufacturer	
	1.3	Product Feature of Equipment Under Test	
	1.4	Product Specification subjective to this standard	
	1.5 1.6	Modification of EUT	
	1.0	Testing Location	
	1.7	Applicable Standards	
	1.0	Applicable Standards	
2	TEST	T CONFIGURATION OF EQUIPMENT UNDER TEST	8
	2.1	Test Mode	8
	2.2	Connection Diagram of Test System	g
	2.3	Support Unit used in test configuration	
	2.4	Measurement Results Explanation Example	g
3	TES	T RESULT	10
	3.1	Conducted Output Power and ERP/EIRP Measurement	10
	3.2	Peak-to-Average Ratio	
	3.3	99% Occupied Bandwidth and 26dB Bandwidth Measurement	
	3.4	Band Edge Measurement	
	3.5	Conducted Spurious Emission Measurement	
	3.6	Field Strength of Spurious Radiation Measurement	
	3.7	Frequency Stability Measurement	56
4	LIST	OF MEASURING EQUIPMENT	60
5	UNC	ERTAINTY OF EVALUATION	62

APPENDIX A. SETUP PHOTOGRAPHS

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 2 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

REVISION HISTORY

REPORT NO.	VERSION	DESCRIPTION	ISSUED DATE
FG491670A	Rev. 01	Initial issue of report	Jan. 06, 2015

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 3 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.1

SUMMARY OF TEST RESULT

Report Section	FCC Rule	IC Rule	Description	Limit	Result	Remark
	§2.1046	RSS-132 (5.4) RSS-133 (6.4)	Conducted Output Power	N/A	PASS	-
3.1	§22.913(a)(2)	RSS-132(5.4) SRSP-503(5.1.3)	Effective Radiated Power	< 7 Watts	PASS	-
	§24.232(c)	RSS-133 (6.4) SRSP-510(5.1.2)	Equivalent Isotropic Radiated Power	< 2 Watts	PASS	-
3.2	§24.232(d)	RSS-132 (5.4) RSS-133(6.4)	Peak-to-Average Ratio	<13 dB	PASS	-
3.3	§2.1049 §22.917(b) §24.238(b)	RSS-GEN(4.6.1) RSS-133(2.3)	Occupied Bandwidth	N/A	PASS	-
3.4	§2.1051 §22.917(a) §24.238(a)	RSS-132 (5.5) RSS-133 (6.5)	Band Edge Measurement	< 43+10log ₁₀ (P[Watts])	PASS	-
3.5	§2.1051 §22.917(a) §24.238(a)	RSS-132 (5.5) RSS-133 (6.5)	Conducted Spurious Emission	< 43+10log ₁₀ (P[Watts])	PASS	-
3.6	§2.1053 §22.917(a) §24.238(a)	RSS-132 (5.5) RSS-133 (6.5)	Field Strength of Spurious Radiation	< 43+10log ₁₀ (P[Watts])	PASS	Under limit 14.11 dB at 5730.000 MHz
2.7	§2.1055 §22.355	RSS-132(5.3)	Frequency Stability for	< 2.5 ppm for Part 22	PASS	
3.7	§2.1055 §24.235	Temperature & Voltage	Within Authorized Band	PA33	-	

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 4 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

1 General Description

1.1 Applicant

DT Research Inc.

6F, NO. 1, NingPo E. St., Taipei, 100 Taiwan, R.O.C.

1.2 Manufacturer

DT Research Inc.

6F, NO. 1, NingPo E. St., Taipei, 100 Taiwan, R.O.C.

1.3 Product Feature of Equipment Under Test

Product Feature				
Equipment	Mobile Tablet			
Brand Name	DT Research Inc.			
Model Name	DT398H			
FCC ID	YE3800C			
	CDMA/EV-DO/LTE			
EUT supports Radios application	WLAN 11a/b/g/n (HT20/HT40)			
	WLAN 11ac (VHT20/VHT40/VHT80)			
	Bluetooth v4.0 EDR/LE			
EUT Stage	Production Unit			

Remark: The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 5 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

1.4 Product Specification subjective to this standard

Product Specification subjective to this standard				
Tx Frequency	CDMA2000 BC0: 824.70 MHz ~ 848.31 MHz CDMA2000 BC1: 1851.25 MHz ~ 1908.75 MHz			
Rx Frequency	CDMA2000 BC0: 869.70 MHz ~ 893.31 MHz CDMA2000 BC1: 1931.25 MHz ~ 1988.75 MHz			
Maximum Output Power to Antenna	CDMA2000 BC0 : 23.93 dBm CDMA2000 BC1 : 23.91 dBm			
99% Occupied Bandwidth	CDMA2000 BC0: 1.28MHz CDMA2000 BC1: 1.28MHz			
Antenna Type	PIFA Antenna			
Antenna Gain	CDMA2000 BC0 : 0.54 dBi CDMA2000 BC1 : 1.18 dBi			
Type of Modulation	CDMA2000 : QPSK CDMA2000 1xEV-DO : QPSK/8PSK			

1.5 Modification of EUT

No modifications are made to the EUT during all test items.

1.6 Maximum ERP/EIRP Power, Frequency Tolerance, and Emission Designator

FCC Rule	System	Type of Modulation	Maximum ERP/EIRP (W)	Tolerance	Emission Designator
Part 22	CDMA2000 BC0 1xRTT	QPSK	0.171	0.0167 ppm	1M28F9W
Part 24	CDMA2000 BC1 1xEV-DO Rev. 0	QPSK	0.323	0.0021 ppm	1M28F9W

 ${\it SPORTON\ INTERNATIONAL\ INC.}$

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 6 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

1.7 Testing Location

Sporton Lab is accredited to ISO 17025 by Taiwan Accreditation Foundation (TAF code: 1190) and the FCC designation No. TW1022 under the FCC 2.948(e) by Mutual Recognition Agreement (MRA) in FCC Test.

Test Site	SPORTON INTERNATIONAL INC.		
	No. 52, Hwa Ya 1 st Rd., Hwa Ya Technology Park,		
Took Cita Lagation	Kwei-Shan Hsiang, Tao Yuan Hsien, Taiwan, R.O.C.		
Test Site Location	TEL: +886-3-327-3456		
	FAX: +886-3-328-4978		
Took Site No.	Sporton Site No.		
Test Site No.	TH02-HY	03CH10-HY	

1.8 Applicable Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- FCC 47 CFR Part 2, 22(H), 24(E)
- ANSI / TIA / EIA-603-C-2004
- FCC KDB 971168 D01 Power Meas. License Digital Systems v02r02
- FCC KDB 412172 D01 Determining ERP and ERIP v01

Remark:

- All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 7 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

2 **Test Configuration of Equipment Under Test**

Test Mode 2.1

Antenna port conducted and radiated test items were performed according to KDB 971168 D01 Power Meas. License Digital Systems v02r02 with maximum output power.

Radiated measurements were performed with rotating EUT in different three orthogonal test planes to find the maximum emission.

Radiated emissions were investigated as following frequency range:

- 30 MHz to 9000 MHz for CDMA2000 BC0.
- 30 MHz to 19000 MHz for CDMA2000 BC1.

All modes and data rates and positions were investigated.

Test modes are chosen to be reported as the worst case configuration below:

Test Modes						
Band	Conducted TCs					
CDMA2000 BC0	■ 1xRTT Link Mode	■ 1xRTT Link Mode				
CDMA2000 BC1	■ 1xEV-DO Rev. 0 Link Mode	■ 1xEV-DO Rev. 0 Link Mode				

Conducted Power Measurement Results:


Conducted Power (*Unit: dBm)							
Band	CI	MA2000 B	C0	CDMA2000 BC1			
Channel	1013	384	777	25	600	1175	
Frequency	824.7	836.52	848.31	1851.25	1880	1908.75	
1xRTT RC1 SO55	23.73	<mark>23.93</mark>	23.71	23.84	23.79	23.74	
1xRTT RC3 SO55	23.61	23.85	23.61	23.87	23.80	23.78	
1xRTT RC3 SO32(+ F-SCH)	23.65	23.89	23.65	23.85	23.81	23.76	
1xRTT RC3 SO32(+SCH)	23.59	23.85	23.58	23.87	23.82	23.79	
1xEV-DO RTAP 153.6kbps	23.59	23.85	23.60	23.91	23.79	23.79	
1xEV-DO RETAP 4096Bits	23.58	23.83	23.57	23.85	23.82	23.77	

SPORTON INTERNATIONAL INC. Page Number : 8 of 62 TEL: 886-3-327-3456 Report Issued Date: Jan. 06, 2015 : Rev. 01 FAX: 886-3-328-4978 Report Version

FCC ID: YE3800C

Report Template No.: BU5-FG22/24 Version 1.1

2.2 Connection Diagram of Test System



2.3 Support Unit used in test configuration

lt	em	Equipment	Trade Name	Model No.	FCC ID	Data Cable	Power Cord
1		System Simulator	R&S	CMU 200	N/A	N/A	Unshielded, 1.8 m

2.4 Measurement Results Explanation Example

For all conducted test items:

The offset level is set in the spectrum analyzer to compensate the RF cable loss and attenuator factor between RF conducted output port and spectrum analyzer. With the offset compensation, the spectrum analyzer reading level will be exactly the RF output level.

The spectrum analyzer offset is derived from RF cable loss and attenuator factor.

Offset = RF cable loss + attenuator factor.

The following shows an offset computation example with RF cable loss 4.2 dB and a 10dB attenuator.

Example:

 $Offset(dB) = RF \ cable \ loss(dB) + attenuator \ factor(dB).$

= 4.2 + 10 = 14.2 (dB)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 9 of 62 Report Issued Date : Jan. 06, 2015

Report No.: FG491670A

Report Version : Rev. 01

3 Test Result

3.1 Conducted Output Power and ERP/EIRP Measurement

3.1.1 Description of the Conducted Output Power and ERP/EIRP Measurement

A system simulator was used to establish communication with the EUT. Its parameters were set to enforce EUT transmitting at the maximum power. The measured power in the radio frequency on the transmitter output terminals shall be reported.

The ERP of mobile transmitters must not exceed 7 Watts for Band 850.

The EIRP of mobile transmitters must not exceed 2 Watts for Band 1900.

According to KDB 412172 D01 Power Approach,

 $EIRP = P_T + G_T - L_C$, ERP = EIRP - 2.15, where

 P_T = transmitter output power in dBm

 G_T = gain of the transmitting antenna in dBi

 L_C = signal attenuation in the connecting cable between the transmitter and antenna in dB


3.1.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.1.3 Test Procedures

- 1. The transmitter output port was connected to the system simulator.
- 2. Set EUT at maximum power through system simulator.
- 3. Select lowest, middle, and highest channels for each band and different modulation.
- 4. Measure the maximum average power for CDMA

3.1.4 Test Setup



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 10 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.1.5 Test Result of Conducted Output Power

Cellular Band ($G_T - L_C = 0.54dB$)						
Modes	CDMA 2000 1xRTT					
Test Status	RC1+SO55					
Channel	1013 (Low)	777 (High)				
Frequency (MHz)	824.70	848.31				
Conducted Power P _⊤ (dBm)	23.73	23.93	23.71			
Conducted Power P _T (Watts)	0.24	0.25	0.23			
ERP(dBm)	22.12	22.32	22.10			
ERP(Watts)	0.163	0.171	0.162			

PCS Band (G _T - L _C = 1.18dB)						
Modes		CDMA 2000 1xEV-DO Rev. 0				
Test Status		RTAP 153.6K				
Channel	25 (Low)	1175 (High)				
Frequency (MHz)	1851.25	1880.00	1908.75			
Conducted Power P _⊤ (dBm)	23.91	23.82	23.79			
Conducted Power P _T (Watts)	0.25	0.24	0.24			
EIRP(dBm)	25.09	25	24.97			
EIRP(Watts)	0.323	0.316	0.314			

Note:

 $EIRP = P_T + G_T - L_C$, ERP = EIRP - 2.15, where

 P_T = transmitter output power in dBm

 G_T = gain of the transmitting antenna in dBi

 L_{C} = signal attenuation in the connecting cable between the transmitter and antenna in dB

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 11 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.2 Peak-to-Average Ratio

3.2.1 Description of the PAR Measurement

The peak-to-average ratio (PAR) of the transmission may not exceed 13 dB.


3.2.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.2.3 Test Procedures

- 1. The testing follows FCC KDB 971168 v02r02 Section 5.7.1.
- 2. The EUT was connected to the spectrum analyzer and system simulator via a power divider.
- 3. Set the CCDF (Complementary Cumulative Distribution Function) option on the spectrum analyzer.
- 4. The highest RF powers were measured and recorded the maximum PAPR level associated with a probability of 0.1 %.
- 5. Record the deviation as Peak to Average Ratio.

3.2.4 Test Setup



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 12 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.2.5 Test Result of Peak-to-Average Ratio

CDMA2000 BC0				
Modes	CDMA 2000 1xRTT			
Channel	1013 (Low) 384 (Mid) 777 (High)			
Frequency (MHz)	824.70	836.52	848.31	
Peak-to-Average Ratio (dB)	4.36	4.24	3.76	

CDMA2000 BC1			
Modes	CDMA 2000 1xEV-DO Rev. 0		
Test Status	RTAP 153.6K		
Channel	25 (Low) 600 (Mid) 1175 (High)		
Frequency (MHz)	1851.25 1880.00 1908.75		
Peak-to-Average Ratio (dB)	3.76	4.12	3.08

 ${\it SPORTON\ INTERNATIONAL\ INC.}$


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 13 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.2.6 Test Result (Plots) of Peak-to-Average Ratio

Band :	CDMA2000 BC0	Test Mode :	1xRTT Link (QPSK)
--------	--------------	-------------	-------------------

Peak-to-Average Ratio on Channel 1013 (824.70 MHz)



Complementary Cumulative Distribution Function (100000 samples) $\mbox{Trace } 1$

Mean 23.11 dBm
Peak 27.70 dBm
Crest 4.59 dB


10 % 2.64 dB
1 % 3.96 dB
.1 % 4.36 dB

4.56 dB

Date: 6.OCT.2014 15:52:59

.01 %

Peak-to-Average Ratio on Channel 384 (836.52 MHz)



Complementary Cumulative Distribution Function (100000 samples) ${\tt Trace} \quad 1$

Peak 27.77 dBm Crest 4.49 dB 10 % 2.60 dB 1 % 3.88 dB .1 % 4.24 dB .01 % 4.44 dB

Mean

23.29 dBm

Date: 6.OCT.2014 15:53:38


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 14 of 62
Report Issued Date : Jan. 06, 2015

Report No.: FG491670A

Report Version : Rev. 01

Peak-to-Average Ratio on Channel 777 (848.31 MHz)



10 % 2.48 dB 1 % 3.40 dB .1 % 3.76 dB .01 % 3.92 dB


Date: 6.OCT.2014 15:54:32

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 15 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

Band: CDMA2000 BC1 Test Mode: 1xRTT Link (QPSK)

Peak-to-Average Ratio on Channel 25 (1851.25 MHz)




Date: 6.OCT.2014 17:12:43

.1 %

Peak-to-Average Ratio on Channel 600 (1880 MHz)

3.76 dB

3.92 dB



Date: 6.OCT.2014 17:13:12

4.12 dB

4.36 dB

.1 %


.01 %

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 16 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

Peak-to-Average Ratio on Channel 1175 (1908.75 MHz)



Crest 3.27 dB

10 % 2.16 dB

1 % 2.88 dB

.1 % 3.08 dB

.01 % 3.20 dB

Date: 6.OCT.2014 17:14:06

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 17 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.3 99% Occupied Bandwidth and 26dB Bandwidth Measurement

3.3.1 Description of 99% Occupied Bandwidth and 26dB Bandwidth Measurement

The 99% occupied bandwidth is the width of a frequency band such that, below the lower and above the upper frequency limits, the mean powers emitted are each equal to a specified percentage 0.5% of the total mean transmitted power.

The emission bandwidth is defined as the width of the signal between two points, located at the 2 sides of the carrier frequency, outside of which all emissions are attenuated at least 26 dB below the transmitter power.


3.3.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.3.3 Test Procedures

- 1. The testing follows FCC KDB 971168 v02r02 Section 4.2.
- 2. The EUT was connected to the spectrum analyzer and system simulator via a power divider.
- 3. The RF output of the EUT was connected to the spectrum analyzer by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 4. The 99% occupied bandwidth were measured, set RBW= 1% of span, VBW= 3*RBW, sample detector, trace maximum hold.
- 5. The 26dB bandwidth were measured, set RBW= 1% of EBW, VBW= 3*RBW, peak detector, trace maximum hold.

3.3.4 Test Setup



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 18 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.3.5 Test Result of Occupied Bandwidth and 26dB Bandwidth

CDMA2000 BC0				
Test Mode	CDMA 2000 1xRTT			
Test Status	RC1+SO55			
Channel	1013 (Low) 384 (Mid) 777 (High)			
Frequency (MHz)	824.70 836.52 848.31			
99% OBW (MHz)	1.28	1.27	1.28	
26dB BW (MHz)	1.41 1.41 1.42			

CDMA2000 BC1				
Test Mode	CDMA 2000 1xEV-DO Rev. 0			
Test Status	RTAP 153.6K			
Channel	25 (Low) 600 (Mid) 1175 (High)			
Frequency (MHz)	1851.25 1880.00 1908.75			
99% OBW (MHz)	1.28	1.27	1.28	
26dB BW (MHz)	1.42	1.42	1.44	

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 19 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.3.6 Test Result (Plots) of Occupied Bandwidth and 26dB Bandwidth


Band: CDMA2000 BC0	Test Mode: 1xRTT_RC1+SO55 (QPSK)	
--------------------	----------------------------------	--

99% Occupied Bandwidth Plot on Channel 1013 (824.7 MHz)



Date: 6.OCT.2014 16:47:59

26dB Bandwidth Plot on Channel 1013 (824.7 MHz)




Date: 6.OCT.2014 16:40:23

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 20 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

99% Occupied Bandwidth Plot on Channel 384 (836.52 MHz)



Date: 6.OCT.2014 16:48:34

26dB Bandwidth Plot on Channel 384 (836.52 MHz)




Date: 6.OCT.2014 16:41:03

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 21 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

99% Occupied Bandwidth Plot on Channel 777 (848.31 MHz)



Date: 6.OCT.2014 16:49:19

26dB Bandwidth Plot on Channel 777 (848.31 MHz)



Date: 6.OCT.2014 16:41:39


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 22 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A


Band: CDMA2000 BC1 Test Mode: 1xEV-DO Rev. 0_RTAP 153.6K (QPSK)

99% Occupied Bandwidth Plot on Channel 25 (1851.25 MHz)



Date: 6.OCT.2014 17:32:12

26dB Bandwidth Plot on Channel 25 (1851.25 MHz)




Date: 6.OCT.2014 17:29:14

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 23 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

99% Occupied Bandwidth Plot on Channel 600 (1880.0 MHz)



Date: 6.OCT.2014 17:32:45

26dB Bandwidth Plot on Channel 600 (1880.0 MHz)




Date: 6.OCT.2014 17:29:47

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 24 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

99% Occupied Bandwidth Plot on Channel 1175 (1908.75 MHz)



Date: 6.OCT.2014 17:33:19

26dB Bandwidth Plot on Channel 1175 (1908.75 MHz)



Date: 6.OCT.2014 17:30:30

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 25 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.4 Band Edge Measurement

3.4.1 Description of Band Edge Measurement

The power of any emission outside of the authorized operating frequency ranges must be lower than the transmitter power (P) by a factor of at least 43 + 10 log (P) dB.

3.4.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.4.3 Test Procedures


- 1. The testing follows FCC KDB 971168 v02r02 Section 6.0.
- 2. The EUT was connected to the spectrum analyzer and system simulator via a power divider.
- The RF output of EUT was connected to the spectrum analyzer by an RF cable and attenuator.
 The path loss was compensated to the results for each measurement.
- 4. The band edges of low and high channels for the highest RF powers were measured.
- 5. The RBW was replaced by 10 kHz, slightly smaller than the value in (2), due to the spectrum analyzer limitation to set the exact value. A worst case correction factor of 10*log (1% emission-BW/measurement RBW) was compensated.
- 6. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.
- 7. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
 - = P(W) [43 + 10log(P)] (dB)
 - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
 - = -13dBm.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 26 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.4.4 Test Setup

<Conducted Band Edge >




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 27 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.1

3.4.5 Test Result (Plots) of Conducted Band Edge

Band: CDMA2000 BC0	Test Mode:	1xRTT_RC1+SO55 (QPSK)
--------------------	------------	-----------------------

Lower Band Edge Plot on Channel 1013 (824.7 MHz)



Date: 6.OCT.2014 16:25:07


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 28 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.1

Band: CDMA2000 BC0 Test Mode: 1xRTT_RC1+SO55 (QPSK)

Higher Band Edge Plot on Channel 777 (848.31 MHz)



Date: 6.OCT.2014 15:58:41


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 29 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

Band: CDMA2000 BC1 Test Mode: 1xEV-DO Rev. 0_RTAP 153.6K (QPSK)

Lower Band Edge Plot on Channel 25 (1851.25 MHz)




Date: 6.OCT.2014 17:26:42

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 30 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.1

Band: CDMA2000 BC1 Test Mode: 1xEV-DO Rev. 0_RTAP 153.6K (QPSK)

Higher Band Edge Plot on Channel 1175 (1908.75 MHz)



Date: 6.OCT.2014 17:17:25

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 31 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.1

3.5 Conducted Spurious Emission Measurement

3.5.1 Description of Conducted Spurious Emission Measurement

The power of any emission outside of the authorized operating frequency ranges must be lower than the transmitter power (P) by a factor of at least 43 + 10 log (P) dB.

It is measured by means of a calibrated spectrum analyzer and scanned from 30 MHz up to a frequency including its 10th harmonic.


3.5.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.5.3 Test Procedures

- 1. The testing follows FCC KDB 971168 v02r02 Section 6.0.
- 2. The EUT was connected to the spectrum analyzer and system simulator via a power divider.
- The RF output of EUT was connected to the spectrum analyzer by an RF cable and attenuator.
 The path loss was compensated to the results for each measurement.
- 4. The middle channel for the highest RF power within the transmitting frequency was measured.
- 5. The conducted spurious emission for the whole frequency range was taken.
- 6. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.
- 7. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
 - = P(W) [43 + 10log(P)] (dB)
 - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
 - = -13dBm.

3.5.4 Test Setup



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 32 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report Template No.: BU5-FG22/24 Version 1.1

3.5.5 Test Result (Plots) of Conducted Spurious Emission

<Low Channel>


Band :	CDMA2000 BC0	Channel:	CH1013
Test Mode :	1xRTT_RC1+SO55 (QPSK)	Frequency:	824.70 MHz

Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 6.OCT.2014 16:51:35

Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 6.OCT.2014 16:51:37

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 33 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 6.OCT.2014 16:51:46

Conducted Spurious Emission Plot between 7GHz ~ 9GHz



Date: 6.OCT.2014 16:51:54


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 34 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

<Middle Channel>


Band :	CDMA2000 BC0	Channel:	CH384
Test Mode :	1xRTT_RC1+SO55 (QPSK)	Frequency:	836.52 MHz

Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 6.OCT.2014 16:52:18

Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 6.OCT.2014 16:52:57

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 35 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 6.OCT.2014 16:53:06

Conducted Spurious Emission Plot between 7GHz ~ 9GHz



Date: 6.OCT.2014 16:53:14

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 36 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

<High Channel>


Band:	CDMA2000 BC0	Channel:	CH777
Test Mode :	1xRTT_RC1+SO55 (QPSK)	Frequency:	848.31 MHz

Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 6.OCT.2014 16:53:53

Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 6.OCT.2014 16:54:06

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 37 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 6.OCT.2014 16:54:14

Conducted Spurious Emission Plot between 7GHz ~ 9GHz



Date: 6.OCT.2014 16:54:23

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 38 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

<Low Channel>


Band :	CDMA2000 BC1	Channel:	CH25
Test Mode :	1xEV-DO Rev. 0_RTAP 153.6K (QPSK)	Frequency:	1851.25 MHz

Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 6.OCT.2014 17:34:35

Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 6.OCT.2014 17:34:11

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 39 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 6.OCT.2014 17:34:54

Conducted Spurious Emission Plot between 7GHz ~ 13.6GHz




Date: 6.OCT.2014 17:35:02

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 40 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

Conducted Spurious Emission Plot between 13.6GHz ~ 19.1GHz



Date: 6.OCT.2014 17:35:11


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 41 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

<Middle Channel>


Band :	CDMA2000 BC1	Channel:	CH600
Test Mode :	1xEV-DO Rev. 0_RTAP 153.6K (QPSK)	Frequency:	1880.0 MHz

Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 6.OCT.2014 17:43:22

Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 6.OCT.2014 17:43:08

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 42 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 6.OCT.2014 17:43:58

Conducted Spurious Emission Plot between 7GHz ~ 13.6GHz




Date: 6.OCT.2014 17:44:06

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 43 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

Conducted Spurious Emission Plot between 13.6GHz ~ 19.1GHz



Date: 6.OCT.2014 17:44:15


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 44 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

<High Channel>


Band :	CDMA2000 BC1	Channel:	CH600
Test Mode :	1xEV-DO Rev. 0_RTAP 153.6K (QPSK)	Frequency:	1880.0 MHz

Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 6.OCT.2014 17:45:16

Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 6.OCT.2014 17:46:07

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 45 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01


Report No.: FG491670A

Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 6.OCT.2014 17:45:37

Conducted Spurious Emission Plot between 7GHz ~ 13.6GHz




Date: 6.OCT.2014 17:45:45

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 46 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

Conducted Spurious Emission Plot between 13.6GHz ~ 19.1GHz



Date: 6.OCT.2014 17:45:54

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 47 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.6 Field Strength of Spurious Radiation Measurement

3.6.1 Description of Field Strength of Spurious Radiated Measurement

The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitter power (P) by a factor of at least 43 + 10 log (P) dB. The spectrum is scanned from 30 MHz up to a frequency including its 10th harmonic.

3.6.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.6.3 Test Procedures

- 1. The testing follows FCC KDB 971168 v02r02 Section 5.8 and ANSI / TIA-603-C-2004 Section 2.2.12.
- 2. The EUT was placed on a rotatable wooden table 0.8 meters above the ground.
- 3. The EUT was set 3 meters from the receiving antenna, which was mounted on the antenna tower.
- 4. The table was rotated 360 degrees to determine the position of the highest spurious emission.
- 5. The height of the receiving antenna is varied between one meter and four meters to search for the maximum spurious emission for both horizontal and vertical polarizations.
- 6. Make the measurement with the spectrum analyzer's RBW = 1MHz, VBW = 3MHz, taking record of maximum spurious emission.
- 7. A horn antenna was substituted in place of the EUT and was driven by a signal generator.
- 8. Tune the output power of signal generator to the same emission level with EUT maximum spurious emission.
- 9. Taking the record of output power at antenna port.
- 10. Repeat step 7 to step 8 for another polarization.
- 11. EIRP (dBm) = S.G. Power Tx Cable Loss + Tx Antenna Gain
- 12.ERP (dBm) = EIRP 2.15
- 13. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.
- 14. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
 - = P(W) [43 + 10log(P)] (dB)
 - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
 - = -13dBm.


Report No.: FG491670A

3.6.4 Test Setup

For radiated emissions from 30MHz to 1GHz



For radiated emissions above 1GHz



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 49 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.1

Report No.: FG491670A

3.6.5 Test Result of Field Strength of Spurious Radiated

<Low Channel>

Band :		CDMA2000	BC0				Tem	perature :		20~22°	С
Test Mode	:	1xRTT_RC1+SO55 (QPSK) Relative Humidity:					ity:	: 47~48%			
Test Engine	eer :	Stan Hsieh, Eric Shih, and Derreck Chen Polarization:					Horizor	ntal			
Remark :		Spurious emissions within 30-1000MHz were found more than 20dB be					low lim	it line.			
Frequency	ERP	Limit	Over	SPA	S.G.	TX Cal	ble	TX Antenna	Polar	ization	Result
			Limit	Reading	Power	loss	5	Gain			
(MHz)	(dBm	1) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(H	1/V)	
1648	-45.7	6 -13	-32.76	-55.29	-47.52	0.98	3	4.89	•	Н	Pass
2472	-46.9	1 -13	-33.91	-60.03	-48.79	1.28	3	5.32		Н	Pass
3296	-52.3	4 -13	-39.34	-68.75	-55.75	1.54	ļ	7.10		Н	Pass

Band :		CDMA2000	BC0				Temp	erature :	20)~22°	С
Test Mode	:	1xRTT_RC	1+SO55	(QPSK) Relative Humidity: 47~48%			6				
Test Engine	eer :	Stan Hsieh	, Eric Sh	nih, and De	rreck Chen	ı	Polari	zation :	Ve	ertical	
Remark :		Spurious emissions within 30-1000MHz were found more than 20dB be						dB belo	w limi	t line.	
Frequency	ERP	Limit	Over	SPA	S.G.	TX Ca	ble T	X Antenna	Polariza	ation	Result
			Limit	Reading	Power	loss	3	Gain			
(MHz)	(dBm	n) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(H/\	')	
1648	-44.8	8 -13	-31.88	-52.33	-46.64	0.98	3	4.89	V		Pass
2472	-46.1	2 -13	-33.12	-61.24	-48	1.28	3	5.32	V		Pass
3296	-57.4	6 -13	-44.46	-73.01	-60.87	1.54		7.10	V		Pass

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 50 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

<Middle Channel>

Band :		CDMA2000	BC0				Temperatur	e:	20~22°	С
Test Mode	:	1xRTT_RC	1+SO55	(QPSK)			Relative Hu	midity:	: 47~48%	
Test Engine	eer:	Stan Hsieh, Eric Shih, and Derreck Chen Polarization :				ı:	Horizontal			
Remark :		Spurious emissions within 30-1000MHz were found more than 20dB be					elow lim	it line.		
Frequency	ERP	Limit	Over	SPA	S.G.	TX Cal	ble TX Ante	nna Pola	rization	Result
			Limit	Reading	Power	loss	s Gair	١		
(MHz)	(dBm) (dBm)	(dB)	(dBm)	(dBm)	(dB) (dBi	(H/V)	
1672	-43.1	0 -13	-30.10	-52.48	-44.78	0.99	4.82		Н	Pass
2512	-48.2	9 -13	-35.29	-61.54	-50.26	1.29	5.41		Н	Pass
3344	-53.2	0 -13	-40.20	-69.3	-56.81	1.56	7.31		Н	Pass

Band :		CDMA2000	BC0				Temp	erature :		20~22°	С
Test Mode	:	1xRTT_RC	C1+SO55 (QPSK) Relative Humidity:				ty:	y : 47~48%			
Test Engine	eer :	Stan Hsieh	, Eric Sh	ih, and De	rreck Chen	ı	Polar	ization :	on:		
Remark :	;	Spurious emissions within 30-1000MHz were found more than 20dB be					dB be	low lim	it line.		
Frequency	ERP	Limit	Over	SPA	S.G.	TX Ca	ble T	X Antenna	Polar	ization	Result
			Limit	Reading	Power	loss	3	Gain			
(MHz)	(dBm) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(H	1 /V)	
1672	-50.42	2 -13	-37.42	-57.62	-52.1	0.99)	4.82		V	Pass
2512	-47.48	3 -13	-34.48	-62.78	-49.45	1.29)	5.41		V	Pass
3344	-58.02	2 -13	-45.02	-73.17	-61.63	1.56	6	7.31		V	Pass

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 51 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.1

Report No. : FG491670A

<High Channel>

Band :		CDMA2000	BC0				Temp	perature :		20~22°C		
Test Mode		1xRTT_RC1+SO55 (QPSK)					Rela	tive Humidi	ty:	6		
Test Engine	eer :	Stan Hsieh	, Eric Sh	nih, and De	rreck Chen		Pola	rization :		Horizontal		
Remark :		Spurious e	Spurious emissions within 30-1000MHz were found more than 20dB below I						low limi	it line.		
Frequency	ERP	Limit	Over	SPA	S.G.	TX Cal	ble TX Antenna Polari		rization	Result		
			Limit	Reading	Power	loss	•	Gain				
(MHz)	(dBm	n) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(H	H/V)		
1696	-40.6	0 -13	-27.60	-50.08	-42.2	1.00)	4.75		Н	Pass	
2544	-41.4	8 -13	-28.48	-55.21	-43.46	1.30)	5.44		Н	Pass	
3392	-49.2	8 -13	-36.28	-65.71	-53.08	1.57	•	7.52		Н	Pass	
4240	-49.4	0 -13	-36.40	-70.72	-54	1.90)	8.65		Н	Pass	

Band :		CDMA2000	0 BC0				Temperature :	20~2	2°C
Test Mode : 1xRTT_RC1			1+SO55	(QPSK)			Relative Humid	ity: 47~4	8%
Test Engin	eer :	Stan Hsieh, Eric Shih, and Derreck Chen Polarization :				Polarization :	Vertic	al	
Remark :		Spurious emissions within 30-1000MHz were found more than 20dB belo				dB below li	mit line.		
Frequency	ERP	Limit	Over	SPA	S.G.	TX Cal	ble TX Antenna	Polarizatio	n Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm) (dBm)	(dB)	(dBm)	(dBm)	(dB) (dBi)	(H/V)	
1696	-46.52	2 -13	-33.52	-54.28	-48.12	1.00	4.75	V	Pass
2544	-42.17	7 -13	-29.17	-57.54	-44.15	1.30	5.44	V	Pass
3392	-54.67	7 -13	-41.67	-70.52	-58.47	1.57	7.52	V	Pass
4240	-52.22	2 -13	-39.22	-72.42	-56.82	1.90	8.65	V	Pass

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 52 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No. : FG491670A

<Low Channel>

Band :		CDMA2000	BC1				Temperature :	20~22	Ω̈́
Test Mode	:	1xEV-DO F	Rev. 0_R	TAP 153.6	K (QPSK)		Relative Humidi	i ty : 47~48°	%
Test Engine	eer :	Stan Hsieh	, Eric Sh	nih, and De	rreck Chen		Polarization :	Horizo	ntal
Remark :		Spurious emissions within 30-1000MHz were found more than 20dB be					dB below lim	it line.	
Frequency	EIRF	Limit	Over	SPA	S.G.	TX Cal	ble TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm	n) (dBm)	(dB)	(dBm)	(dBm)	(dB) (dBi)	(H/V)	
3700	-39.6	1 -13	-26.61	-58.26	-46.18	1.67	8.24	Н	Pass
5555	-33.9	4 -13	-20.94	-57.61	-41.01	2.66	9.72	Н	Pass
7403	-41.2	7 -13	-28.27	-70.06	-50.42	2.46	11.61	Н	Pass

Band :		CDMA2000	BC1				Tem	perature :		20~22°	С	
Test Mode	:	1xEV-DO F	Rev. 0_R	TAP 153.6	K (QPSK)		Rela	tive Humidi	ty:	: 47~48%		
Test Engine	eer:	Stan Hsieh	, Eric Sh	ih, and De	rreck Chen		Pola	rization :		Vertica		
Remark :		Spurious e	missions	within 30-	1000MHz v	vere fou	ınd m	nore than 20d	dB be	low lim	it line.	
Frequency	EIRP	Limit	Over	SPA	S.G.	TX Ca	ble	TX Antenna	Polar	ization	Result	
			Limit	Reading	Power	loss	\$	Gain				
(MHz)	(dBm) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(H	1/V)		
3700	-44.6	3 -13	-31.63	-63.19	-51.2	1.67	7	8.24		V	Pass	
5555	-36.93	3 -13	-23.93	-59.05	-44	2.66	6	9.72		V	Pass	
7403	-46.3	1 -13	-33.31	-74.73	-55.46	2.46	6	11.61		V	Pass	

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 53 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No. : FG491670A

<Middle Channel>

Band :		CDMA2000	BC1				Tem	perature :		20~22°	С	
Test Mode		1xEV-DO Rev. 0_RTAP 153.6K (QPSK) Relative Humidity: 47~48%				6						
Test Engine	eer :	Stan Hsieh	, Eric Sh	ih, and De	rreck Chen		Pola	rization :		Horizontal		
Remark :		Spurious e	missions	within 30-	1000MHz v	were fou	ınd m	ore than 20	dB be	low lim	it line.	
Frequency	EIRF	Limit	Over	SPA	S.G.	TX Ca	ble	TX Antenna	Pola	rization	Result	
			Limit	Reading	Power	loss	3	Gain				
(MHz)	(dBm	n) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(I	1 /V)		
3763	-35.4	7 -13	-22.47	-54.62	-42.1	1.69)	8.32		Н	Pass	
5639	-28.4	0 -13	-15.40	-52.22	-35.45	2.71		9.76		Н	Pass	
7522	-42.0	8 -13	-29.08	-70.76	-51.47	2.42	2	11.81		Н	Pass	

										ī
Band :		CDMA2000	BC1				Temperature :	nperature: 20~22°		
Test Mode		1xEV-DO F	Rev. 0_R	D_RTAP 153.6K (QPSK) Relative Humidity: 47~48%				%		
Test Engine	er:	Stan Hsieh	, Eric Sh	ih, and Dei	and Derreck Chen Polarization : Vertical				l	
Remark :		Spurious e	missions	within 30-	1000MHz v	vere fou	and more than 20	dB bel	ow lim	it line.
Frequency	EIRF	Limit	Over	SPA	S.G.	TX Ca	ble TX Antenna	Polar	ization	Result
			Limit	Reading	Power	loss	Gain			
(MHz)	(dBn	n) (dBm)	(dB)	(dBm)	(dBm)	(dB) (dBi)	(H	/V)	
3763	-38.4	3 -13	-25.43	-57.06	-45.06	1.69	8.32		V	Pass
5639	-32.9	8 -13	-19.98	-55.27	-40.03	2.71	9.76		V	Pass
7522	-46.5	5 -13	-33.55	-74.84	-55.94	2.42	11.81		V	Pass

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 54 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No. : FG491670A

<High Channel>

ngii Onaiii												
Band :		CDMA2000	BC1				Tempe	rature :	:	20~22°C		
Test Mode		1xEV-DO Rev. 0_RTAP 153.6K (QPSK) Relative Humidity: 47~48%					6					
Test Engine	eer:	Stan Hsieh	, Eric Sh	ih, and De	rreck Chen	l	Polariz	ation :	Horizontal			
Remark :		Spurious e	missions	within 30-	1000MHz \	were fou	ınd more	e than 20	dB be	low lim	it line.	
Frequency	EIRF	Limit	Over	SPA	S.G.	TX Ca	ble TX	Antenna	Polar	ization	Result	
			Limit	Reading	Power	loss	3	Gain				
(MHz)	(dBm	n) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(⊦	I /V)		
3819	-37.8	4 -13	-24.84	-57.38	-44.52	1.70)	8.38		Н	Pass	
5730	-27.1	1 -13	-14.11	-51.23	-34.14	2.76	6	9.79		Н	Pass	
7634	-42.0	2 -13	-29.02	-70.48	-51.51	2.39)	11.88		H	Pass	

Band :		CDMA2000	BC1				Tem	perature :		20~22°	С	
Test Mode	:	1xEV-DO F	Rev. 0_R	TAP 153.6	K (QPSK)		Rela	tive Humidi	ty:	47~48%		
Test Engine	eer:	Stan Hsieh	, Eric Sh	ih, and De	rreck Chen		Pola	rization :		Vertical		
Remark :		Spurious e	missions	within 30-	1000MHz v	vere fou	ınd m	nore than 20d	dB be	low lim	it line.	
Frequency	EIRP	Limit	Over	SPA	S.G.	TX Ca	ble	TX Antenna	Polar	ization	Result	
			Limit	Reading	Power	loss	5	Gain				
(MHz)	(dBm) (dBm)	(dB)	(dBm)	(dBm)	(dB)	(dBi)	(H	1/V)		
3819	-40.0	1 -13	-27.01	-58.69	-46.69	1.70)	8.38		V	Pass	
5730	-29.2	5 -13	-16.25	-52.41	-36.28	2.76	6	9.79		V	Pass	
7634	-43.9	8 -13	-30.98	-72.06	-53.47	2.39)	11.88		V	Pass	

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 55 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No. : FG491670A

3.7 Frequency Stability Measurement

3.7.1 Description of Frequency Stability Measurement

The frequency stability shall be measured by variation of ambient temperature and variation of primary supply voltage to ensure that the fundamental emission stays within the authorized frequency block. The frequency stability of the transmitter shall be maintained within ±0.00025% (±2.5ppm) of the center frequency.

3.7.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.7.3 Test Procedures for Temperature Variation

- 1. The testing follows FCC KDB 971168 v02r02 Section 9.0.
- 2. The EUT was set up in the thermal chamber and connected with the system simulator.
- With power OFF, the temperature was decreased to -30°C and the EUT was stabilized before testing. Power was applied and the maximum change in frequency was recorded within one minute.
- 4. With power OFF, the temperature was raised in 10°C steps up to 50°C. The EUT was stabilized at each step for at least half an hour. Power was applied and the maximum frequency change was recorded within one minute.


3.7.4 Test Procedures for Voltage Variation

- 1. The testing follows FCC KDB 971168 v02r02 Section 9.0.
- 2. The EUT was placed in a temperature chamber at 25±5° C and connected with the system simulator.
- 3. The power supply voltage to the EUT was varied from BEP to 115% of the nominal value measured at the input to the EUT.
- 4. The variation in frequency was measured for the worst case.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 56 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.7.5 Test Setup



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 57 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.1

Report No.: FG491670A

3.7.6 Test Result of Temperature Variation

Band:	CDMA2000 BC0 1xRTT_RC1+SO55	Channel:	384
Limit (ppm):	2.5	Frequency:	836.52 MHz

Temperature (°C)	Deviation (ppm)	Result
50	0.0167	
40	0.0108	
30	0.0024	
20(Ref.)	0.0000	
10	0.0012	PASS
0	0.0024	
-10	0.0012	
-20	0.0084	
-30	0.0036	

Band :	CDMA2000 BC1 1xEV-DO Rev. 0_RTAP 153.6K	Channel:	600
Limit (ppm):	within authorized band	Frequency:	1880.0 MHz

Temperature (°C)	Deviation (ppm)	Result
50	0.0011	
40	0.0016	
30	0.0011	
20(Ref.)	0.0000	
10	0.0021	PASS
0	0.0016	
-10	0.0005	
-20	0.0005	
-30	0.0000	

Note: The frequency fundamental emissions stay within the authorized frequency block based on the frequency deviation measured is small.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 58 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

3.7.7 Test Result of Voltage Variation

Band & Channel	Mode	Voltage (Volt)	Deviation (ppm)	Limit (ppm)	Result
		132	0.0108		
CDMA2000 BC0 CH384	1xRTT RC1+SO55	120	0.0072	2.5	Dana
C11304	KC1+3033	BEP	0.0084		
	1xEV-DO	132	0.0005		Pass
CDMA2000 BC1 CH600	Rev. 0	120	0.0000	(Note 3.)	
C11000	RTAP 153.6K	BEP	0.0011		

Note:

- 1. Normal Voltage = 132V.
- 2. Battery End Point (BEP) = 120 V.
- 3. The frequency fundamental emissions stay within the authorized frequency block based on the frequency deviation measured is small.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 59 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A

4 List of Measuring Equipment

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Test Date	Due Date	Remark
Base Station	Rohde & Schwarz	CMU200	117591	GSM/GPRS/WCD	Oct. 23, 2013	Dec. 15, 2014~	Oct. 22, 2015	Radiation (03CH10-HY)
Notch Filter	Wainwright	WRCG1710/ 1755-1690/17	SN2	AWS Band	Oct. 01, 2014	Dec. 15, 2014~ Dec. 18, 2014	Sep. 30, 2015	Radiation
Notch Filter	Wainwright	WRCG824/8 49-40/8SS	SN35	CDMA 850	Oct. 01, 2014	Dec. 15, 2014~ Dec. 18, 2014	Sep. 30, 2015	Radiation (03CH10-HY)
Notch Filter	Wainwright	WRCT1850/1 910-40/8SS	SN21	1900	Oct. 01, 2014	Dec. 15, 2014~ Dec. 18, 2014	Sep. 30, 2015	Radiation
Filter	Wainwright	WLKS1200-8 SS	SN3	1.2G Low Pass	Oct. 01, 2014	Dec. 15, 2014~	Sep. 30, 2015	Radiation
Filter	Microwave	H3G018G1	SN477220	3.0G High Pass	Oct. 01, 2014	Dec. 15, 2014~ Dec. 18, 2014	Sep. 30, 2015	Radiation (03CH10-HY)
Amplifier	SONOMA	310N	187311	0.1MHz~1000MHz	Nov. 24, 2014	Dec. 15, 2014~	Nov. 23, 2015	Radiation (03CH10-HY)
Bilog Antenna	TESEQ	CBL 6111D	35413	30MHz~1GHz	Oct. 24, 2014	Dec. 18, 2014 Dec. 15, 2014~ Dec. 18, 2014	Oct. 23, 2015	Radiation (03CH10-HY)
Hygrometer	TECPEL	DTM-303B	TP140320	N/A	Nov. 17, 2014	Dec. 15, 2014~ Dec. 18, 2014	Nov. 16, 2015	Radiation (03CH10-HY)
Preamplifier	Keysight	83017A	MY53270078	1GHz~26.5GHz	Nov. 20, 2014	Dec. 15, 2014~ Dec. 18, 2014	Nov. 19, 2015	Radiation (03CH10-HY)
Spectrum Analyzer	Keysight	N9010A	MY54200485	N/A	Oct. 14, 2014	Dec. 15, 2014~ Dec. 18, 2014	Oct. 13, 2015	Radiation (03CH10-HY)
Double Ridged Guide Horn	SCHWARZBEC K	BBHA 9120 D	9120D-1325	1GHz ~ 18GHz	Oct. 03, 2014	Dec. 15, 2014~ Dec. 18, 2014	Oct. 02, 2015	Radiation (03CH10-HY)
Base Station (Measure)	Anritsu	MT8820C	6201432817	N/A	Oct. 28, 2014	Dec. 15, 2014~ Dec. 18, 2014	Oct. 27, 2015	Radiation (03CH10-HY)
RF Cable	HUBER + SUHNER	SUCOFLEX 104	MY24956/4 MY24952/4M	30MHz~1GHz	Nov. 06, 2014	Dec. 15, 2014~ Dec. 18, 2014	Nov. 05, 2015	Radiation (03CH10-HY)
RF Cable	HUBER + SUHNER	SUCOFLEX 104	MY249564 MY249524MY	1GHz~25GHz	Nov. 06, 2014	Dec. 15, 2014~ Dec. 18, 2014	Nov. 05, 2015	Radiation (03CH10-HY)
Controller	EMEC	EM 1000	N/A	1m-4m	N/A	Dec. 15, 2014~ Dec. 18, 2014	N/A	Radiation (03CH10-HY)
Antenna Mast	EMEC	AM-BS-4500- B	N/A	N/A	N/A	Dec. 15, 2014~	N/A	Radiation (03CH10-HY)
Turn Table	EMEC	TT 2200	N/A	0-360 degree	N/A	Dec. 15, 2014~ Dec. 18, 2014	N/A	Radiation (03CH10-HY)
Filter	Wainwright	WHKX1.5/15 G-10SS	SN31	1.5G High Pass	Oct. 01, 2014	Dec. 15, 2014~	Sep. 30, 2015	Radiation
Signal Generator	Rohde & Schwarz	SMF100A	101107	100kHz~40GHz	May. 23, 2014	Dec. 18, 2014 Dec. 15, 2014 Dec. 18, 2014	May. 22, 2015	(03CH10-HY) Radiation (03CH10-HY)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 60 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A



Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Test Date	Due Date	Remark
Spectrum Analyzer	Rohde & Schwarz	FSP40	100055	9kHz~40GHz	Jun. 09, 2014	Oct. 06, 2014	Jun. 08, 2015	Conducted (TH02-HY)
Thermal Chamber	Ten Billion	TTH-D3SP	TBN-930701	N/A	Jul. 17, 2014	Oct. 06, 2014	Jul. 16, 2015	Conducted (TH02-HY)
LTE Base Station	Anritsu	MT8820C	6201026480	30MHz~2.7GHz SISO	Jan. 07, 2014	Oct. 06, 2014	Jan. 06, 2015	Conducted (TH02-HY)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 61 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No. : FG491670A

5 Uncertainty of Evaluation

Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)

Measuring Uncertainty for a Level of	4.90
Confidence of 95% (U = 2Uc(y))	4.90

Uncertainty of Radiated Emission Measurement (1 GHz ~ 40 GHz)

Measuring Uncertainty for a Level of	5.50
Confidence of 95% (U = 2Uc(y))	

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3800C Page Number : 62 of 62
Report Issued Date : Jan. 06, 2015
Report Version : Rev. 01

Report No.: FG491670A