
4. Internal Photograph of the Host


Host: (Brand Name: DT Research Inc. / Model Name: DT395)

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 9 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01


Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 10 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01



Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 11 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01


Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 12 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01



Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B

Page Number


: 13 of 16

Report Issued Date : Jan. 17, 2013

Report Version

: Rev. 01


Report No.: EP2D0508-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 14 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 15 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YE3600B Page Number : 16 of 16
Report Issued Date : Jan. 17, 2013
Report Version : Rev. 01