Report No: HK10110996-2

Configuration Photographs

Worst-Case Radiated Emissions

(Front View) Receiving mode

Model: TS03RC



INTERTEK TESTING SERVICE

Report No: HK10110996-2

Configuration Photographs

Worst-Case Radiated Emissions

(Back View) Receiving mode

Model: TS03RC



INTERTEK TESTING SERVICE

Report No: HK10110996-2

Configuration Photographs

Worst-Case Radiated Emissions

(Front View) Charging mode

Model: TS03RC



INTERTEK TESTING SERVICE

Report No: HK10110996-2

Configuration Photographs

Worst-Case Radiated Emissions

(Back View) Charging mode

Model: TS03RC

