

## AiSai Communication Technology Co., Ltd

Suite 2610, 26/F., Asia Trade Center, 79 Lei Muk Road, Kwai Chung, N.T. Hong Kong Tel: (852)27909165 Email: <u>DP-xing@aisaicom.com</u>

URL: www.aisaicom.com

Fax: (852)23451164

12th October 2011

**Federal Communications Commission** 

Subject: Declare for YHHIPLKA01 interference issue

To Whom It May Concern,

This is to declare that the device in FCC identified: YHHIPLKA01 has been block for avoid interference to Mobile Satellite Service.

We hereby ensure that the operation modes mentioned in page 3 to 6 of Manual as the below:

- (i) Access Point and Access Point WDS Mode
- (ii) Access Point WDS Mode
- (iii) Station Mode
- (iv) Station WDS Mode
- (v) Router Mode
- (vi) Repeater WDS Mode
- (i), (ii), & (vi) modes above are only for indoor use, the program allows the user or selects automatically to use channel from 5150-5250MHz when the user selects (i), (ii), & (vi) operation modes. For other modes, the channel in 5150-5250MHz must be disable and can't be selected from the program.

To my best of Knowledge, the above declared is true.

We hope this satisfies your requirements as identified and we look forward to receiving your confirmation.

Sincerely,

Dapeng Xing Technique Manag