

Appendix A. Setup Photographs

<Conducted Emission>

Mode 3



Mode 4



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : A1 of A3
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report No.: FC651207


Report Template No.: BU5-FC15B Version 1.3

C Test Report No. : FC651207

Mode 1

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : A2 of A3
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC651207

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : A3 of A3
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3