

Report No. : FD181517

## Appendix B. Setup Photographs

## <Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBJR Page Number : B1 of B2
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01






**Report No. : FD181517** 

## <Radiated Emission>





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSAMBJR Page Number : B2 of B2 Report Issued Date: Nov. 30, 2011 Report Version : Rev. 01