

**Report No. : FC291002** 

# Appendix B. Setup Photographs

# <Conducted Emission>

### Mode 2



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35

: B1 of B2 Page Number Report Issued Date: Sep. 26, 2012 Report Version : Rev. 01




# <Radiated Emission>

### Mode 4

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35 Page Number : B2 of B2
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 01

Report No.: FC291002